



Maintenance & Inspection Division

March 2018 Update

Vegetation Removal

Coordinated with CIP on Russian Olive Removal on Cherry Creek Reach 2



W-5



Inverness Regional Pond

East Tollgate Creek @ Dove Hill



Reservoir Pond (Pond 1)

Vegetation removal



Before



After



Before



After



Before Big Dry Creek @ Dry Creek Rd. Outfall Repair



This section shows the 'Before' state of the project. It includes an aerial map with a red circle indicating the location at the intersection of Big Dry Creek and Dry Creek Rd. Two photographs show the initial site conditions: a yellow excavator clearing a steep, wooded embankment, and a concrete pipe being prepared for installation in a trench, with orange safety netting visible.

After Big Dry Creek @ Dry Creek Rd. Outfall Repair



This section shows the 'After' state of the project. Two photographs show the completed work: a concrete pipe installed in a trench, and a close-up view of the pipe's outlet, showing the finished structure.

Cottonwood Creek @ Brairwood

Sediment Removal



Camera Van

- 98,000 Linear feet of pipe have been inspected
- Since February of 2017 we have located:
 - 23 Utility Intrusions
 - 8 Potential IDDE connections
 - 3 Sinkholes



Jamison Culvert



Inspections



Deficiencies Mean Time to Resolution by Period



Sky Ranch



VICINITY MAP
SCALE: 1" = 2000'



Grass Swale at Encompass

